

# CertAlert

DOT/Federal Aviation Administration, Southern Region Airports Division,  
Airport Certification Safety Team (ASO-620), P.O. Box 20636, Atlanta, Georgia 30320  
(404) 305-6700; FAX: (404) 305-6730

Issued April 29, 2015

Number SO-15-02

This CertAlert pertains to:  
14 CFR part 139 Airport Operators

## Due Dates for Airport Markings

The table below shows due dates for applying standards outlined in FAA Advisory Circular 150/5340-1L, dated September 27, 2013.

Note: "Next paint cycle" means the next time the affected markings are re-painted.

Change	When to Complete	AC reference
Add black borders to runway markings on light colored pavement	By 9/27/15	Paragraph 1.4(a) Table 1-2
New marking removal standards (larger box area)	Effective for any removal after 9/27/13	Paragraph 1.3(f) Figures 1-1, 1-2, 1-3, 1-4
Replace existing ramp control markings with new standard	Next paint cycle	Paragraph 4.12; marking is optional Figures 4-1, 4-2, 4-3, 4-4, 4-5
Taxiway edge markings to be interrupted for Pattern A and B holding position markings	Next paint cycle	Paragraph 4.4(e)(4) and 3.4(d)(3) Figure A-13
Taxiway edge markings to be interrupted for Pattern C holding position markings	Next paint cycle, but no later than 9/27/16	Paragraph 3.6(d) Figure A-18(refers to Figure A-13)
Taxiway edge marking to be interrupted for non-movement area boundary marking	Next paint cycle	Paragraph 5.4(e)(4) and (e)(5)
Pattern A and C holding position marking dashes centered on taxiway centerline marking	Next paint cycle	Paragraph 3.3(d)(1) and 3.6(d) Figures A-13, A-14

Change	When to Complete	AC reference
Pattern B marking vertical bars equidistant from the taxiway centerline marking	Next paint cycle	Paragraph 3.5(d) Figure A-13
Provide sufficient space between closely installed markings(ex. 2 foot minimum spacing between vehicle roadway and non-movement area boundary marking)	Next paint cycle, but no later than 9/27/16	Paragraph 1.3(a) and 5.2(c)
Enhanced Taxiway Centerline Marking; removal of last set of partial dashes before point of tangency on a merge	Next paint cycle	Paragraph 4.3(d)(3) Figure D-13
Runway threshold markings start 20 feet from the start of the runway threshold	Next paint cycle (preferred) or Next runway resurfacing project	Paragraph 2.5(a) and (c) Figures A-1, A-2, A-7, A-8, A-9
Remove surface markings intended for aircraft from vehicle roadways	Next paint cycle, but no later than 9/27/16	Paragraph 5.2(a)
Spacing of runway markings for intersecting runways	Next paint cycle	Figure A-5